

# habitability evidence packet — unit 4B

Generated 2026-01-02T09:30:00Z · 3 media item(s), 3 trusted-timestamped · producer 9636-7c84-aed5-ab6f

This packet documents habitability conditions. It is evidence, not legal advice, and it does not guarantee admissibility. Integrity is independently checkable against the accompanying **bundle.json** with the **habitable verify** tool.

## Issue: Black mold on ceiling

Category: mold · Room: bathroom · Severity: high · Status: open

### *Timeline*

- **observed:** Mold spreading after roof leak
- **sent\_request:** Emailed landlord requesting repair




Captured 2026-01-02T09:15:00Z · hash d283e0b6b0a6411b... · timestamped



Captured 2026-01-02T09:15:00Z · hash 687fead7fb018d53... · timestamped

## Issue: No heat

Category: heat · Room: bedroom · Severity: urgent · Status: open



Captured 2026-01-02T09:15:00Z · hash 83668853a196988e... · timestamped

# Evidence appendix

Each item lists its content hash, trusted-timestamp status, and custody status. These verify independently against bundle.json.

Capture	Content hash (SHA-256)	Timestamp	Authority
cap-001767312000006. 000000.a561aba556288 8f6	d283e0b6b0a6411b2a97856c3456bc93340e40dfd7e4a1a33 1a0d4acf4f97929	verified	demo-rfc3161-tsa
cap-001767312000010. 000000.a561aba556288 8f6	687fead7fb018d53824056eb84a6ab694d40f51e4280f42cf0a dc1518ff4adf1	verified	demo-rfc3161-tsa
cap-001767312000014. 000000.a561aba556288 8f6	83668853a196988ed3563461e7c5efa0cc5b4ebdb93b30073 b3b0cb69a6de149	verified	demo-rfc3161-tsa